

Outfall Number	Drainage Basin	Landuse	Associated With	Outfall Type	Quantity	Size (inches)	Inspection Date
OUT-001	UPPER HUDSON RIVER BASINS	Suburban Res	None	Closed Pipe	Single	36	12/30/2009
Submerged	Material	Inlet	Discharges Into	48 hrs Rainfall	Flow Present	Flow Description	Deposits\Stains
No	CMP	Catch Basin	Flowing Stream	.50 to 1.00	Yes	Substantial	No
Benthic Growth	Abnormal Vegetation	Pool Quality	Outfall Damage	Characterization (Illicit Discharge)	Street or Nearest Location		
Green	No	No	No	Unlikely	CROTON AVE		

**Remarks**

Condition: Good - Maintenance Needed: No - Notes:

