

# Land Disturbance Impacts of improving McManus Rd.

10x large diameter trees [between 24" – 40"]

2x medium diameter trees [between 10" – 20"]

Pictures current as of 9/29/22

**Green outline** bordering McManus Road (Reference: Cronin Engineering) depicts estimated area of land disturbance considering (1) removal of existing asphalt, (2) installation of wider driveway, and (3) installation of utilities. In addition to 12 trees, a family garden, custom built fencing, improved paving stone & concrete driveway entrances, existing mailboxes, and some stone walls will need to be removed.

